

# **U2** Wearable smart computer

## Unleash new possibilities



#### Hands-free scanning

Add a R7 ring scanner worn on a finger to U2 wearable smart computer, enables workers to keep their hands and eyes on the items they are handling. With these new wearable, not only work efficiency and task accuracy is improved, the user comfort experience is also greatly enhanced.

#### Fast data connectivity

Supports 4G and 3G cellular radio, and 802.11a /b/g/n WiFi, and Bluetooth 4.1

### Wide Range of Applications

U2 is widely used in our life. It is convenient and practical Applicable to warehouse management, logistics control and other scenarios Can be matched with Bluetooth Scale/Printer/Ring Scanner and other peripherals



# **SPECIFICATIONS**

Basic Characteristics				
O.S	Android 7.1			
CPU	Quad-Core 1.2GHz			
Display	4.0 inch TFT-LCD WVGA (480 × 800) color screen			
Panel	Support Multiple finger touch, gloves touch.			
RAM	2GB			
ROM	16GB			
Dimensions	118mm×91mm×33mm			
Weight	275g (Included battery and wristband)			
Buttons	Context Button, Home Button, Back Button, 2 User definable buttons (F1, F2), Button, power button			

Power	Power		
Main Battery	Rechargeable 3.7V 2850 mAh		
Charging time	less than 4 hours		
RTC Battery	Real time clock battery		

Radio Communication				
Wi-Fi	802.	802.11 a/b/g/n wireless communication		
Bluetooth	Blue	Bluetooth 4.1+BLE		
International	4G	FDD-LTE:Band1/2/3/4/5/7/8/20/28A/28B TDD-LTE:Band38/39/40/41		
Version	3G	WCDMA(Band1/2/5/8)		
	2G	GSM/EDGE:850/900/1800/1900MHz		

Expansion	Expansion and peripherals	
Camera	8MP camera with LED flash and auto-focus function; Support camera scanning	
GPS	GPS, A-GPS, BDS, GLONASS	
Slot	Micro SD/TF, Micro SIM	
Interfaces	3.5mm Audio port, Magnetic pogo pin (With USB and charging functions, Support wired scanner)	

Accessorie	Accessories		
Audio	Loadspeaker, Microphone		
Standard Accessories	Power adaptor, USB-Magnetic pogo pin data cable, Instructions, Wristband		
Optional Accessories	Ring Scanner, Cradle		

User Environment	
Operating Temperature	-10~50℃
Storage Temperature	-20∼70℃
Humidity	5% ~ 95% (non condensing)

### Accessories







Cradle

Ring Scanner

